



Fiber Optics Installer® (FOI®) & Technician® (FOT®)

ETA® **suggested** equipment list

1. OTDR with launch and receive cables
2. Fusion Splicer
3. Optical Loss Test Set (OLTS)
4. Inspection scope
5. Mandrel
6. Jumper
7. Mating Sleeves
8. Continuity Tester
9. Visual Fault Locator (VFL)

As an ETA® Fiber Optic training approved school this list is a guideline and can be customized for your application.